

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 7137

CR NO. 32

OVER THE

WATSON SAG CHANNEL

DISTRICT 8 - CHIPPEWA COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY
COLLINS ENGINEERS, INC.

JOB NO. 3512 (CEI 92)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units at Bridge No. 7137, Piers 1 through 6, were found to be in satisfactory condition with minor splitting and checking of the timber members. Several of the timber diagonal cross braces were split through the connection to the timber piles or broken off completely. The steel piles were in good condition and displayed only a light layer of corrosion from just above the waterline to the channel bottom. The timber pile cap at Pier 1 has been replaced since the previous inspection. The channel bottom around the substructure units appeared to be in stable condition with no evidence of significant scour or appreciable changes since the previous inspection.

INSPECTION FINDINGS:


- (A) The timber piles were in satisfactory condition. The piles were typically weathered with minor splitting and checking over the entire height of the pile with maximum widths of 1/4 inch and maximum penetrations of 1 inch.
- (B) In several locations across the structure, the timber bracing was split through the pile fasteners and/or broken off completely.
- (C) The steel piles were generally in good condition with light corrosion observed from 3 feet above the waterline to the channel bottom with some random pitting having a maximum penetration of 1/16 inch.
- (D) Two piles were split above the waterline at Pier 6. Pile B was split from the top of the pile to 2 feet above the waterline with a maximum width of 3/4 inch and up to 3 inches of penetration. Pile D was split from the top of the pile to 8 feet above the waterline with a maximum width of 1/2 inch and up to 1 inch of penetration.

RECOMMENDATIONS:

- (A) Replace the split and/or broken diagonal timber cross bracing to restore the lateral stability of the structure.
- (B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg

A large, stylized handwritten signature of Daniel G. Stromberg, written in black ink, positioned below the printed name and above the date and registration number.

Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature of Daniel G. Stromberg, written in black ink, positioned below the company name and above the printed name and title.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 7137

Feature Crossed: The Watson Sag Channel

Feature Carried: CR No. 32

Location: District 8 - Chippewa County

Bridge Description: The superstructure consists of seven multiple timber beam spans. The superstructure is supported by six piers composed of six timber piles and two steel shell piles, and two timber abutments. The piers are labeled 1 through 6 starting from the south end of the bridge.

2. INSPECTION DATA

Professional Engineer/Team Leader: Shirley M. Walker, P.E.

Dive Team: Michelle D. Koerbel, Clayton G. Brookins

Date: October 31, 2002

Weather Conditions: Sunny, " 15EF

Underwater Visibility: Negligible/None

Waterway Velocity: Negligible/None

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 through 6.

General Shape: The piers consist of a timber pile cap supported by a single row of six timber piles and two steel pipe piles. The steel piles, on the east side of the bridge, appear to be associated with a deck widening after original construction.

Maximum Water Depth at Substructure Inspected: Approximately 10.2 Feet.

4. WATERLINE DATUM

Water Level Reference: Top of pile cap on the west end of Pier 6.

Water Surface: The waterline was approximately 10.3 feet below reference.
Waterline Elevation = 933.7.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 6



Item 61: Channel and Channel Protection: Code 8

Item 92B: Underwater Inspection: Code B/10/02

Item 113: Scour Critical Bridges: Code I/95

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

_____ Yes X No



SOUNDING PLAN

TYPICAL END VIEW OF PIERS

GENERAL NOTES:

1. Piers 1 through 6 were inspected underwater.
2. At the time of inspection on October 31, 2002, the waterline was located approximately 10.3 feet below the top of the pile cap at the downstream end of Pier 6. This corresponds with a waterline elevation of 933.7 based on the previous report dated September 25, 1997.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken along the bridge at the midpoints between the substructure units.

INSPECTION NOTES:

- 1 The channel bottom material consisted of sandy silt and scattered 6 inch diameter riprap with up to 3 inches of probe rod penetration.
- 2 Light corrosion was observed on the steel piles from 3 feet above the waterline to the channel bottom with random minor pitting having a maximum penetration of 1/16 inch.
- 3 Minor splitting and checking of the timber piles was observed from the pier cap to the channel bottom with a maximum width of 1/4 inch and a maximum penetration of 1 inch.
- 4 Diagonal timber bracing was split through the fastener.
- 5 Abrasion damage observed on the timber pile, from 1.0 foot above the waterline to 2.5 feet below the waterline, approximately 8 inches wide with a maximum penetration of 0.5 inch.
- 6 Delamination on outer shell of timber pile was observed around the waterline with maximum penetration of 1/2 inch.
- 7 Split in pile, from the top of the pile cap to 8 feet above the waterline with a maximum width of 1/2 inch and 1 inch of penetration.
- 8 Split in pile, from the pile cap to 2 feet above the waterline with a maximum width of 3/4 inch and 2 to 3 inches of penetration.
- 9 Diagonal bracing broken and no longer attached to pile.
- 10 Piles E and F at Pier 2 were replaced with three steel H-Piles connected with steel bracing.

Legend


- 2.0 Sounding Depth from Waterline (10/31/02)
-5.2 Sounding Depth from Waterline (9/25/97)
- () Timber Pile (under cap)
() Battered Timber Pile (under cap)
() Steel Encased Concrete Pile (under cap)
() Battered Steel Encased Concrete Pile (under cap)
- A Pile Identification Designation
I Steel H-pile

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 7137
OVER THE WATSON SAG CHANNEL
DISTRICT 8, CHIPPEWA COUNTY

INSPECTION AND SOUNDING PLAN

Drawn By: PRH	COLLINS ENGINEERS, INC.	Date: OCT. 2002
Checked By: MDK	300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Scale: NTS
Code: 35120092		Figure No.: 1



INSPECTION NOTES:

- 1 The channel bottom material consisted of sandy silt and scattered 6 inch diameter riprap with up to 3 inches of probe rod penetration.
- 2 Light corrosion was observed on the steel piles from 3 feet above the waterline to the channel bottom with random minor pitting having a maximum penetration of 1/16 inch.
- 3 Minor splitting and checking of the timber piles was observed from the pier cap to the channel bottom with a maximum width of 1/4 inch and a maximum penetration of 1 inch.
- 4 Diagonal timber bracing was split through the fastener.
- 5 Abrasion damage observed on the timber pile, from 1.0 foot above the waterline to 2.5 feet below the waterline, approximately 8 inches wide with a maximum penetration of 0.5 inch.
- 6 Delamination on outer shell of timber pile was observed around the waterline with maximum penetration of 1/2 inch.
- 7 Split in pile, from the top of the pile cap to 8 feet above the waterline with a maximum width of 1/2 inch and 1 inch of penetration.
- 8 Split in pile, from the pile cap to 2 feet above the waterline with a maximum width of 3/4 inch and 2 to 3 inches of penetration.
- 9 Diagonal bracing broken and no longer attached to pile.

$\frac{-2.0}{-5.2}$	<i>Sounding Depth from Waterline (10/31/02)</i>
	<i>Sounding Depth from Waterline (9/25/97)</i>
()	<i>Timber Pile (under cap)</i>
()—	<i>Battered Timber Pile (under cap)</i>
⊗	<i>Steel Encased Concrete Pile</i>
⊗—	<i>Battered Steel Encased Concrete Pile</i>
<div style="border: 1px solid black; padding: 2px; display: inline-block;">A</div>	<i>Pile Identification Designation</i>
I	<i>Steel H-pile</i>

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**


STRUCTURE NO. 7137
OVER THE WATSON SAG CHANNEL
DISTRICT 8, CHIPPEWA COUNTY

INSPECTION AND SOUNDING PLAN


Drawn By: PRH
Checked By: MD
Code: 35I20092

COLLINS ENGINEERS, INC.
 300 W. WASHINGTON, STE. 600
 CHICAGO, ILLINOIS 60606
 (312) 704-9300

Date: OCT. 2002
Scale: NTS
Figure No.: 2



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note: _____
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 7137 OVER THE WATSON SAG CHANNEL DISTRICT 8, CHIPPEWA COUNTY UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH	 COLLINS ENGINEERS, INC. 300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: OCT. 2002
Checked By: MDK		Scale: 1"=20'
Code: 35I20092		Figure No.: 3



Photograph 1. Overall View of the Structure, Looking Southeast.



Photograph 2. View of Pier 1, Looking Northwest.



Photograph 3. View of Upstream End of Piers 2, 3, and 4, Looking Southeast.



Photograph 4. View of Pier 5, Looking Southeast.



Photograph 5. View of Pier 6, Looking Southeast.



Photograph 6. Overall View of Structure, Looking Southwest.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: October 31, 2002
ON-SITE TEAM LEADER: Shirley M. Walker, P.E.
BRIDGE NO: 7137 WEATHER: Sunny, " 15EF
WATERWAY CROSSED: The Watson Sag Channel
DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
OTHER

PERSONNEL: Michelle D. Koerbel, Clayton G. Brookins
EQUIPMENT: Scuba, U/W Light, Lead Line, Scraper, Probe Rod, Sounding Pole, Camera
TIME IN WATER: 7:50 a.m.
TIME OUT OF WATER: 8:10 a.m.
WATERWAY DATA: VELOCITY Negligible/None
VISIBILITY Negligible/None
DEPTH 10.2 feet maximum at Pier 2.

ELEMENTS INSPECTED: Piers 1 through 6

REMARKS: Overall, the timber and steel piles were in satisfactory condition below water. The timber piles were typically weathered with minor splitting and checking up to 1/4 inch wide and up to 1 inch deep. Several of the timber diagonal cross braces were split through the connection to the timber piles or broken off completely. The steel piles were in good condition and displayed only a light layer of corrosion with minor random pitting from the waterline to the channel bottom. The channel bottom around the substructure units appeared to be in stable condition with no evidence of significant scour or appreciable changes since the previous inspection. The timber pile cap at Pier 1 has been replaced since the previous inspection.

FURTHER ACTION NEEDED: X YES NO

Replace the split and/or broken diagonal timber cross bracing to restore the lateral stability of the structure.

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 7137
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Shirley M. Walker, P.E.
WATERWAY CROSSED The Watson Sag Channel

INSPECTION DATE October 31 2002
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING (TIMBER)	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL (PILES)	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	6.0'	6	N	N	8	7	6	8	8	8	8	8	N	7	6	7	7	N
	Pier 2	10.2'	6	N	N	8	6	6	8	N	N	8	8	N	7	6	7	N	N
	Pier 3	9.1'	6	N	N	8	6	6	8	N	N	8	8	N	7	6	7	N	N
	Pier 4	6.9'	6	N	N	8	6	6	8	N	N	8	8	N	7	6	7	N	N
	Pier 5	8.0'	6	N	N	8	6	6	8	N	N	8	8	N	7	6	7	N	N
	Pier 6	5.0'	6	N	N	8	7	6	8	8	8	8	8	N	7	6	7	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the timber and steel piles were in satisfactory condition below water. The timber piles were typically weathered with minor splitting and checking up to 1/4 inch wide and up to 1 inch deep. Several of the timber diagonal cross braces were split through the connection to the timber piles or broken off completely. The steel piles were in good condition and displayed only a light layer of corrosion with minor random pitting from the waterline to the channel bottom. The channel bottom around the substructure units appeared to be in stable condition with no evidence of significant scour or appreciable changes since the previous inspection. The timber pile cap at Pier 1 has been replaced since the previous inspection.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.